

How to Convert ppb to ppm to Percent

ppm/ppb/percent

10 ppb = 0.000001%

10 ppb = 0.01 ppm

100 ppb = 0.00001%

0.1 ppm = 100 ppb

1 ppm = 0.0001%

10 ppm = 0.001%

100 ppm = 0.01%

1,000 ppm = 0.1%

10,000 ppm = 1.0%

100,000 ppm = 10.0%

1,000,000 ppm = 100.0%

